


The blank is prepared for turning between centres on the woodwork lathe.

Reduce the blank to a uniform 40 mm diameter prior to shaping.

A turnery template should be used for assessment purposes, if required. Use of woodworking lathe (between centres) to a given diameter to ±1mm

(N5) or ±2mm (N4)



N4: Operation Tolerance

Marking out 2mm Planing or similar 2mm Constructing - joint gaps not to exceed 2mm Flat-frame - overall sizes within 5mm

N5: Operation Tolerance

Marking out 1mm Planing or similar 1mm Constructing - joint gaps not to exceed 1mm Flat-frame - overall sizes within 3mm